







Illuminated
button
spring-return

Indicator light

Illuminated
button
spring-return

Contacts		Diagram
Device 1	1NO	
Device 2	/	
Device 3	1NO	



Connector	M12 with 12 pole at the bottom	
-----------	-----------------------------------	--