



Illuminated
button
spring-return

Illuminated
button
spring-return

Illuminated
button
spring-return

Illuminated
button
spring-return

REARM

	Contacts	Diagram	Connections
Device 1	1NO		
Device 2	1NO		
Device 3	1NO		
Device 4	1NO		

Connector	M12 with 12 pole at the bottom	
-----------	-----------------------------------	--

